

K-factors in advance p 5

Exterior Connections?  
Stay Dry with Longer Probes

Downloads & Drivers p 3  
Try Simulation p 11

Optional Install Kit: AC-104  
All the handy install parts


### Installing with a Laptop On-Site

- p 2 Hardware Layout / Specifications
- p 3 Step I: Software Prep and Assembly
- p 4 Step II: Tracking
- p 5 Step III: K-factor

**\*\*** Step IV: Configure Communication  
See separate "Data Transmission Instructions"  
<https://vataverks.com/support/>  
for Modbus, MQTT, Pulse, Data Logging, HTTP Publish

### Supplementary Information

- p 7 K-Factor discovery
- p 9 Installing without a Laptop On-Site
- p 10 Command Menus
- p 11 Troubleshooting  
Desk Top Simulation  
Signal Strength
- P 12 Sensor Placement



### Models : (F)eatures, (O)ptions


VV – 100 – 00 – G		
VV – 100 – 02/07/15 – G		
F	1 A	Ribbon Probe Gas: 18" Indoor ONLY
F	1 B	Remote Probe Gas: 2M, 7M, 15M length
F F	2	Meter Strap
F	3 A	Probe Coupler Indoor (1) (VVA-113)
O	3 B	Probe Coupler Outdoor (VVA-114)
O	4	Probe Extension (user supplied CAT6)
F 5, 6		Probe Pigtail + Strain relief
F F	7	VV-100 Main Unit
F F	9 A	Power1 + 36" USB Cable
O O	9 A	10ft USB Cable Option (VVA-108-120)
F F	9 B	Power2
F F	10	USB Wall Plug: (not shown)
F F	11 A	Ethernet output
F F	11 B	Pulse output
F F	11 C	Modbus RTU output
O O	VVA-020	Optional Ultra-Hi-Res. Output

**OUTDOOR/WET METER LOCATIONS APPROVED WHEN INSTALLED WITH REMOTE SENSOR PROBE**  
Confirm Meter Compatibility Before Invasive Site Work. See Instructions or Contact Vata Verks  
**NOT FOR USE IN HAZARDOUS OR EXPLOSIVE ENVIRONMENTS**

VataVerks reserves the right to alter product offerings and specifications at any time without notice and is not responsible for errors that may appear in this document.

## HARDWARE LAYOUT / SPECIFICATIONS

### BOARD COMPONENTS



### COMPONENTS

- A. Ribbon Probe Connection
- B. Ethernet connection
- C. Mini-USB connection (configuration /power)
- D. Reset Button: Paperclip accessible  
LEDs blink off when actuated.
- E. SD Card
- F. Jumper switch (U15)
- G. 3.7V Lithium Backup battery
- H. 15 Position terminal block
- I. Sensor chip location (Ribbon Probe Shown)
- J. Remote Sensor switches (U14)

### LED Key

Slow = 1.0 second blink  
Fast = 0.3 second blink

#### Error (yellow):

- Off: running a command (ex: tracking)
- Slow: unit in idle state. Waiting for command
- Fast: unit is reading amplitude.
- Solid: hard fault including low bus voltage

#### Status

- Fast: calibrating phase of tracking
- Solid: tracking phase of tracking

#### USB

- Off: USB port inactive or faulted (PC error)
- Slow / Fast: USB transmitting & receiving

#### Bat

- Off: battery is fully charged
- Fast: bus voltage too low to support operation
- On: battery charging or no battery present

#### Com1 (Reserved)

#### Com2 (Remote Probe: Tracking / Amplitude mode)

- Solid: communicating with Probe
- Slow: failing to Communicate (check wiring)
- Off: not in Tracking or Amplitude mode

### VV-100 SPECIFICATIONS

**Water Version: VV-100-XX-W**

#### Water Meter Compatibility

All positive displacement, piston, compound, multi-jet, single jet  
**Incompatible:** Solid state / Ultra-sonic / Sensus Omni: see VV-200 series

**Gas Version: VV-100-XX-G**

#### Gas Meter Compatibility

All diaphragm, rotary, turbine.  
**Incompatible:** Ultra-sonic

#### Data Protocols

- Modbus-TCP via Ethernet
- Modbus-RTU via Term. Block
- Telnet via Ethernet
- MQTT via Ethernet
- Pulse via Term. Block
- HTTP Publish via Ethernet
- Data Log via Onboard

#### Resolution (in meter revolutions)

- 1 rev Standard
- 1/100<sup>th</sup> rev Optional

#### Accuracy (12 month)

- Water Meter: >99%
- Gas Meter: >97%

#### Control and Management

- Local: via USB cable
- Remote: via Telnet / Web

#### Installation Limits

- -20C to 40C
- 10% - 95% RH non-condensing
- Not for hazardous locations

#### Main Unit and Ribbon Probe

- Indoor / Dry
- Length: 1.5 ft ribbon cable

#### Remote Probe

- Outdoor, immersion, burial
- Max extended: 200 ft CAT6

#### Power Consumption

- 300mA Max

#### Power Options

- 5V via USB to wall adaptor
- +5VDC 1Amp via Term. Block
- Available 12 - 24V via converter


#### Backup Battery: Recharg 3.7V Li-ion

- Backup life vs probe length  
12hr@2 ft, 6hr@100 ft, 1hr@200 ft

#### Certifications

Complies with Part 15 of FCC Rules

### UNIT COMPONENTS



## I. SOFTWARE PREP AND HARDWARE ASSEMBLY



### 0. Partially Charge Battery (Optional)

Open top. Confirm battery is secure in place.  
Use USB cable & wall plug adapter to wall charge unit for at least 10

### 1. Download Terminal Emulator & FTDI Driver

For **Windows OS: Tera Term** (PuTTY and other emulators may be used)

1. Go to: <https://download.cnet.com/>
2. Enter: "Tera Term" in the **Download** search bar.
3. **Download and Install** with default settings
4. Go to: <https://ftdichip.com/>
5. Navigate to **Drivers** then **VCP** and Download Driver  
If Windows: Download "**Setup Executable**" under Comments.
6. **Reboot Laptop**



### 2. Assemble Unit and Connect Laptop

1. Connect **Ribbon OR Remote** Probe to Unit. Not both. (See right)
2. Connect to laptop with the mini-USB cable. LEDs blink.
3. **DO NOT** connect Ethernet port to laptop or Remote Probe.

### 3. Configure "Tera Term"

#### **PROBE MUST BE CONNECTED FIRST**


1. Open **Tera Term**.
2. Click **Setup** for dropdown
3. Choose **Serial Port...**
4. **Configure** as shown right
5. At **Port\*** Choose the Com#.
6. Click **New Open**
7. Click Black Screen. **ENTER**
  - I. **Username: admin ENTER**
  - II. **Password: admin ENTER****NOTE: If Password appears first, hit ENTER**
8. **M> ENTER** for Command Directory
9. **T ENTER** for Tracking Directory  
*(try Desk-Top Simulation pg 11 to become familiar)*



**\*If Port prompt is "grey", and unit is connected to laptop via serial port as directed above, your laptop's FTDI Driver may be missing /incorrect. Recheck above.**  
**\*\*Your Tera Term configuration can be saved. At Setup dropdown: click "Save Setup"**

#### To Connect Ribbon Probe

**VV-100-00-G**  
Plug Ribbon Cable  
Probe into Main



#### To Connect Remote Probe

**VV-100-0X-G**  
Wire Remote Probe Cat6  
cable to terminal strip


1




Remove screws + cover  
Find Switch **U14**  
**Switch 1 to "ON"**  
(confirm battery is secure)

2

Wire Pigtail to  
Terminal Strip



3



Affix **Strain Relief** to side.  
Zip tie **Pigtail** to **Strain Relief**

4



Connect Probe to Pigtail  
using supplied Coupler

If extending the Probe's Cat6 cable:  
Probe End-to-Main Unit Max Length = 200 ft  
Requires additional Coupler.

## INSTALLING WITH A LAPTOP



### II. Tracking (Counting Meter Revolutions)

#### PRO TIP

- When Meter is distant from Main Unit's final location, consider a temporary set-up at Meter with laptop to locate Probe, and discover Meter K-factor (if unknown).
- All installations on Meters larger than Model Size 1000 (any brand) should follow this Tip.

#### Tracking Meter Revolutions

1. Gas should flow this step\*  
Safely use Gas equipment per appliance instructions.  
*Higher flow = faster tracking*
2. Strap the sensor to the meter. See pg 12 for location.
3. **To Calibrate or Re-Calibrate**  
At Tracking Menu type:
  - x **ENTER** Wait for "Function complete"  
Keeps calibration & rev. count
  - r **ENTER** Deletes calibration & rev. count
  - t **ENTER** Calibrates and starts tracking  
\*If Flow=0, unit will Auto-Calibrate and Track whenever flow starts.

*It takes 15 - 30 seconds to track on Diaphragm Meters displaying revolution count every 5 seconds.*
4. Strap or Zip Tie sensor in place. (permanently)  
Zip tie Probe cable to adjacent pipe as strain relief.  
  
If sensor moves. **Re-Calibrate.** (see above)

If discovering K-factor on-site. Start Now pg 5, 7 Otherwise:  
\*\*\*\* **Stop Gas Flow** \*\*\*\*  
See pg 5 to Configure Communications

**Having Trouble Tracking? Refer to:**  
**Signal Strength or Troubleshooting pg 11**

Data Displayed with Successful Tracking	
SLOW METER	FASTER METER
TRACK:x Function complete	TRACK:x Function complete
TRACK:r Track	TRACK:r Track
TRACK:t Start Tracking	TRACK:t Start Tracking
TRACK: P1	TRACK: P1
P2	P2
P3	P3
P4	P4
P5	P5
Signal Measured: 1850	Signal Measured: 4538
Z Dominate	Z Dominate
Rev=0.00 rev	Rev=7.00 rev
Rev=0.00 rev	Rev=23.00 rev
Rev=1.00 rev	Rev=44.00 rev
Rev=2.00 rev	Rev=66.00 rev
Rev=3.00 rev	<u>Rev=87.53 rev</u>
<u>Rev=4.67 rev</u>	Rev=108.19 rev
Rev=5.80 rev	

Transition to Ultra Hi-Res Output  
If unit equipped with this option

Calibrating

Tracking

#### To Start or Stop the Display feed

- 3 **ENTER** to stop reporting to the screen
- 2 **ENTER** to re-start reporting to the screen

**INSTALLING WITH A LAPTOP**



**III. K-Factor (Converting Revolutions to Flow Volume)**

**▶ Converting Revolutions to Flow Volume**

**K-Factor = Meter capacity in Revolutions / Unit Volume (ex: 9.2 revs / ft<sup>3</sup>)**  
K-Factor converts Revolution Count to Flow Volume.

**A: REQUEST YOUR K-FACTOR**

Nearly ALL Diaphragms Meters  
have been Pre-Measured.

1.

If pre-measured, we will share the K-factor with you.  
Email to: [info@vataverks.com](mailto:info@vataverks.com)



- 1) Your Name, Company, Mobile #
- 2) Installation City, state
- 3) Photo of VV-100 Barcode Label
- 4) Photo of Meter + Meter Data Plate

**NOTE: One K-factor response per barcode.**  
**Day-of-Install requests not recommended.**

**B: DISCOVER YOUR K-FACTOR**

On-Site or Off-Site

**Pg 7: Option 1. Calculated on the Meter**

- On-Site
- Requires Gas Flow
- Requires 10 minutes
- and your FULL UNDIVIDED ATTENTION

**Pg 8: Option 2. Calculated using Utility Bills**

- Off-Site
- Requires 32 – 60 days.

**How to Use the K-Factor**

**FOR MODBUS, MQTT, HTTP**

**To Transmit Volume**

- 1) Enter K-factor in Tracking Menu
- 2) NOTE: If K-factor <1.0, See top pg 7.

**Or Transmit Revolutions**

- 3) Apply K-factor to your Revolution data in the Cloud

**FOR PULSE**

**To Pulse per Standard Volume (ex: 1 pulse / 10 ft<sup>3</sup>)**

- 1) Use K-factor to calculate Pulse K-factor. Enter in Pulse Menu

**Or Pre-program Pulse K-Factor (ex: 10 revs / pulse)**

- 2) Use K-factor to calculate resulting Volume per Pulse.

**Remember to SAVE Often: ‘S’ ENTER**

**IV. Configure Communications**

**With K-Factor Known and Sensor Probe Strapped in Place**

**TO COMPLETE THIS  
INSTALLATION**

- To Configure Communication for:  
MQTT, Modbus-TCP, Modbus-RTU, Pulse, HTTP Publish, Data Logging, Telnet:  
See “Data Transmission Instructions” found at <https://vataverks.com/support/>
- If Communication is configured and data received, transfer to permanent power
  - Transfer USB Cord with Wall Adaptor to wall outlet
  - OR Optional 5VDC to terminal Strip (pg 2)

## **SUPPLEMENTARY INFORMATION**



**PRO TIP**

Increasing Tracking display rate from 5 seconds to 1 second can increase accuracy of your K-factor data.

In Tracking Menu:

- + **ENTER** expands Menu
- b(space)**1.0 ENTER** sets display rate to 1/sec.  
return to 5 second rate when finished

**If K-Factor < 1.0**

The VV-100 requires a K-factor of 1.0 or greater.  
If K-factor is <1.0: Multiply both sides by 10.

Example: If a meter K-factor is: 0.33 Revs / ft<sup>3</sup>  
Convert K-factor to: 3.3 Revs / 10 ft<sup>3</sup>.

**OPTION 1: K-Factor Calculated using the Meter**

K-Factor = (Revolutions from the Vata Verks Display) / (Flow Volume from the Meter Register).  
But Diaphragm Meters don't have 10's & 1's displayed. The solution is the 1/2 ft<sup>3</sup> leak detection dial.


**Gas must be flowing for this step.** Safely use gas appliance or heating system

**1**


**To START K-Factor Measurement**

At the EXACT moment the Vata Verks Sensor outputs a new rev. (ex. From 3.00 to 4.00)  
**Simultaneously** record rev. count from PC Display and take a photo of the 1/2 ft<sup>3</sup> Meter Register

Vata Verks Display



4.00 rev




0.65 turn  
(5 is estimated)


**2**

Count the "turns" of the 1/2 ft<sup>3</sup> dial. Do not walk away. The meter is not recording 1/2 ft<sup>3</sup> turns.

Vata Verks Display



Count Carefully



3.00 turns


**3**

\*Note: More revolutions, More "turns" = higher accuracy K-Factor


**To STOP K-Factor Measurement**

At the EXACT moment the Vata Verks Sensor outputs a new rev. (ex. from 16.00 to 17.00)  
**Simultaneously** record rev. count from PC Display and take a photo of the 1/2 ft<sup>3</sup> Meter Register.

Vata Verks Display



17.00 rev



0.62 turn  
(2 is estimated.)

**\*\*\*\* Gas Flow Can Be Turned OFF \*\*\*\***

**OPTION 1: K-Factor Calculated on the Meter: Continued**

**1** **Flow Volume from the ½ ft<sup>3</sup> Dial of the Meter**

$$0.65 \text{ turn} + 3.00 \text{ turn} + 0.62 \text{ turn} = 4.27 \text{ turn} / 2^* = 2.135 \text{ ft}^3$$

\*Important to convert from ½ ft<sup>3</sup> to full ft<sup>3</sup>

**2** **Revolutions from Vata Verks Display**

$$17.00 \text{ rev} - 4.00 \text{ rev} = 13.00 \text{ rev}$$

**3** **Revolutions / Flow Volume = K-Factor**

$$13.00 \text{ rev} / 2.135 \text{ ft}^3 = 6.08 \text{ revs/ ft}^3$$

**OPTION 2: K-Factor Calculated Using the Utility Bill.**  
No meter read or on-site laptop required.

**1** Install Sensor. Use your archived sensor data with 1 fully Sensor Tracked Utility Bill period.

$$\text{Revolutions} = (\text{Rev. Count LAST day}^* \text{ of utility bill}) - (\text{Rev. Count 1st day}^* \text{ of bill})$$

**2**

$$\text{Flow Volume (ft}^3\text{)} = \text{Therms used from the monthly bill} \times 96.7 \text{ ft}^3 \text{ per Therm}$$

**3**

$$\text{Revolutions} / \text{Flow Volume (ft}^3\text{)} = \text{K-Factor (revs/ ft}^3\text{)}$$

2 consecutive "Actual" Meter Reads required. No Estimated reads.

2nd Utility Bill must START after the date of installation.

\*Time of Billing Period START / STOP is unknown. Use 12:00 Noon when choosing Vata Verks Sensor data.

Adding subsequent months will improve accuracy.

Months with low gas usage are unsuitable because of the low 100 ft<sup>3</sup> resolution of Diaphragm Meters.

**Return to pg 5 to Apply K-Factor and complete the installation.**







**PRO TIP: Installing Units without a laptop On-Site**

Use Simulation pg 11 to familiarize before sending to field.

**PRO TIP: Installing Units with Remote Probe**

For Meters larger than 1000 (any brand). Temporarily set up at Meter to confirm tracking. A laptop is suggested for larger meters.



**Setting up the Main Unit**

1. **Unit MUST** be Assembled and Configured Off-Site (pg 3)  
**See Instructions: Configuring Data Transmission at:**  
<https://vatawerks.com/support/>
2. Strap Probe to meter. Refer to **Sensor Placement Maps** (pg 12).
3. Connect Power: USB wall adaptor OR 5VDC to terminal strip. LEDs will be ON.
4. **Gas MUST flow through Meter THIS STEP.**  
Gently Depress Reset with paperclip. LEDs will blink off. (pg 2)  
With **Reset**, Unit will auto-Calibrate then track with flow  
**(If Flow=0, unit will Auto-Calibrate and Track when flow starts)**
5. **COM2** LED solid if Remote Probe is Communicating.  
**Status** LED blinks if Calibrating. Solid if Tracking Flow  
**\*\*\*\* Gas Flow Can be Turned OFF \*\*\*\***
6. Zip Tie Probe Cable to pipe as strain relief. Permanently
7. Finish: Affix Main Unit in a dry location.
8. If MQTT, Modbus, HTTP: Connect Ethernet cable to Gateway
9. If Pulse: Wire twisted pair from terminal strip to Pulse counter
10. If unit Sensor Probe was unplugged, or unit lost power Step 8 -10, Reset the device. Repeat steps 4, 5, 6.
11. Confirm data is being received.
12. Discover K-Factor (see below)

**Failure to Calibrate?**

- Option 1** Reposition Probe: try again. Repeat Steps 4 through 12
- Option 2** A Telnet connected colleague can help identify the strongest magnetic field location ([pg 11](#))

**Options to Discover K-Factor without a Laptop**

- A. From Vata Verks K-factor archive (pg 5)
- B. Using Monthly Bills (pg 8)
- C. Real-time tracking data received in office (pg 7)  
with Simultaneous meter reads in the field.

Supplementary Information -

**COMMAND MENU REFERENCE**

**\*\*MAIN MENU\*\***

**M** - Main Menu

**T** - Tracking menu

**C** - Communication menu

**N** - Network menu

**P** - Pulse Output menu

**Z** - Device maintenance menu

**g** - Logout

**x** - Exit current function

**S** - Save configuration

Some configuration parameters require a reset to take effect

**M** – Return to Main Menu

**SEE BELOW**

*(to configure for Modbus, MQTT, HTTP Publish)*

*(to configure for Modbus, MQTT, Telnet)*

*(to configure for Pulse)*

**SEE BELOW**

**SAVE OFTEN**

See Instructions:  
**Configuring Data  
Transmission**

**T ENTER**

**\*\*TRACKING MENU\*\***

**a** - Signal Strength (requires flow)

*measure magnetic field strength*

**t** - Start tracking (requires flow)

**x** - Stop Tracking or Signal Strength

**r** - Reset tracker to 0, deletes calibration

**k** - Enter meter K factor rev/unit volume (k xxx.xxx)

*for entering k factor. Will not accept k-factor <1.0. see pg 7.*

**v** - Set Units (gal, ft3, m3, rev) (v gal)

*K-factor can be any unit of volume. This takes note of the choice.*

**2** - Start reporting data to screen

**3** - Stop reporting data to screen

**+** - Show Advanced Functions

*So many other features*

**S** - Save configuration

**SAVE OFTEN**

Some configuration parameters require a reset to take effect

**M** – Return to Main Menu

**Z ENTER**

**\*\*MAINTENANCE MENU\*\***

**a** - Start Tracking on powerup

*default is enabled.*

**c** - Display current configuration – all

*useful information*

**v** - Display Version Information

*useful information: Serial Number and firmware build*

**b** - Display device info and battery status

*displays programmed time*

**R** - Reset Board

**soft Reset: saves tracking+count. (hard button Reset does not)**

**f** - Restore factory defaults

*(Note: Push button Reset deletes Calibration and Tracking)*

**r** - Reload last saved configuration

**p** - Save path file

**m** - Record signal strength (SEE INSTR)

**w** - Enable/Disable Web Server

*Default is enabled*

**u** - Set device username and password

**t** - Set Time of day 24Hr format (t yyyy:mm:ddThh:mm:ss) *programming time*

**k** - Unlock features

*admin Use*

**S** - Save configuration

**SAVE OFTEN**

Some configuration parameters require a reset to take effect

**M** – Return to Main Menu



## Trouble / Causes / Corrections

1. **Attempting to Track**  
Displays: "Start Tracking"  
Does not display: P1, P2 etc showing calibration.
  - a. No flow through meter?
  - b. Sensor not strapped to meter?
  - c. Magnetic Signal too weak: (see Right)
  - d. Meter incompatible
2. **Attempting to Track**  
Displays: "Start Tracking"  
Display repeats over and over P1, P2, P3, P4, P5
  - a. Flow happening, but magnetic field too weak.
  - b. Find Stronger Field (see Right)
3. **Attempting to Track**  
Does not display "Start Tracking"
  - a. Repeat the steps x, r, t (see pg 4)
  - b. Wait for "Function Complete" after "x", before "r"
4. **Will not track. Though Magnetic Field is strong.**
  - a. Go to Z Menu, and Reset "R" the device.
5. **"Sensor Stall" warning**
  - a. Check that Sensor is correctly wired.
  - b. Reset the device
6. **"Remote Sensor Not Found" warning or COM2 LED blinking**
  - a. Check that Sensor is correctly wired
  - b. Go to Z Menu, and Reset "R" the device.
7. **LED's are OFF, though Power is ON**
  - a. Unscrew top, Find Switch U15, Confirm all OFF.
  - b. Reset the Unit with Push Button
8. **K-Factor Entered on Tracking Menu**  
Displays: **\*\*Invalid Data Entry\*\***
  - a. K-factor <1.0 is not accepted by VV-100
  - b. Use 10X. Ex: 0.3 rev/ft3 = 3.3 rev / 10 ft3
  - c. Enter 3.3, and take note of 10 ft3.
9. **Forgot Password or Username**
  - a. Contact Vata Verks for instructions

## Desk Top Simulation

Sensor function simulated using Earth's magnetic field.

From Tracking Menu:

### Simulate Tracking

- A) Holding probe in hand
- B) x ENTER to stop function
- C) r ENTER to delete calibration
- D) t ENTER to calibrate / track
- E) Roll sensor back and forth (as below)



### Measure Magnetic Fields

- A) a ENTER to measure field
- B) Move sensor or pass objects by probe

## Find Meter's Strongest Signal Location

### Gas Flow Required

At Tracking Menu:

- a ENTER measures field strength

*Seek highest last number in the series.*

Hold Probe to meter for multiple readings then move to new location.

If Output is:

- A) 9,11,9,25 no signal or no flow
- B) 27,5,34,175 low, but ok for diaphragm
- C) 111,47,267,382 >275 is good
- D) 0,630,0,2500 >2000 can be too strong\*

\*If too strong, either:

- A) w ENTER disables Boost
- B) Move Probe to weaker location

**Found a suitable location?**

**Repeat Tracking pg 4**

Supplementary Information

**SENSOR PLACEMENT**

**Sensor Placement: Recommendation**

In any first trial, Sensor Probe should be placed:

- Centered Vertically / Horizontally
- Front or Back

Examples below.

Use “Signal Strength” feature (pg 11) if other sensor locations must be found.

If placing the Probe on the top of the meter, K-factor must be measured on the meter.

**Having a problem, or have a question?**

Email: [info@vataverks.com](mailto:info@vataverks.com)



**Strapping Probe to Meter**

- Rubber strap (included in kit)
- And /Or
- Zip ties (do not damage probe)
- Adhesive strain reliefs

**Send Your Installation Photos and K-Factors**

Help us improve our products and services.