

Installing with a Laptop On-Site

- p 2 Hardware Layout / Specifications
- p 3 Step I: Software Prep and Assembly
- p 4 Step II: Tracking
- p 5 Step III: K-factor

**** Step IV: Configure Communication**
See separate "Data Transmission Instructions"
<https://vataverks.com/support/>
for Modbus, MQTT, Pulse, Data Logging, HTTP Publish

Supplementary Information


- p 7 K-Factor discovery
- p 9 Installing without a Laptop On-Site
- p 10 Command Menus
- p 11 Troubleshooting
Desk Top Simulation
Signal Strength
- P 12 Sensor Placement / Meter Reading

Downloads & Drivers p 3
Try Simulation p 11

K-factors in advance p 5

Optional Install Kit: AC-104
All the handy install parts

Exterior Connections?
Stay Dry with Longer Probes



Models : (F)eatures, (O)ptions


VV – 100 – 00 – G		
VV – 100 – 02/07/15 – G		
F	1 A	Ribbon Probe Gas: 18" Indoor ONLY
F	1 B	Remote Probe Gas: 2M, 7M, 15M length
F F	2	Meter Strap
F	3 A	Probe Coupler Indoor (1) (VVA-113)
O	3 B	Probe Coupler Outdoor (VVA-114)
O	4	Probe Extension (user supplied CAT6)
F 5, 6		Probe Pigtail + Strain relief
F F	7	VV-100 Main Unit
F F	9 A	Power1 + 36" USB Cable
O O	9 A	10ft USB Cable Option (VVA-108-120)
F F	9 B	Power2
F F	10	USB Wall Plug: (not shown)
F F	11 A	Ethernet output
F F	11 B	Pulse output
F F	11 C	Modbus RTU output
O O	VVA-020	Optional Ultra-Hi-Res. Output

OUTDOOR/WET METER LOCATIONS APPROVED WHEN INSTALLED WITH REMOTE SENSOR PROBE
Confirm Meter Compatibility Before Invasive Site Work. See Instructions or Contact Vata Verks
NOT FOR USE IN HAZARDOUS OR EXPLOSIVE ENVIRONMENTS

VataVerks reserves the right to alter product offerings and specifications at any time without notice and is not responsible for errors that may appear in this document.

HARDWARE LAYOUT / SPECIFICATIONS

BOARD COMPONENTS



COMPONENTS

- A. Ribbon Probe Connection
- B. Ethernet connection
- C. Mini-USB connection (configuration /power)
- D. Reset Button: Paperclip accessible
LEDs blink off when actuated.
- E. SD Card
- F. Jumper switch (U15)
- G. 3.7V Lithium Backup battery
- H. 15 Position terminal block
- I. Sensor chip location (Ribbon Probe Shown)
- J. Remote Sensor switches (U14)

LED Key

Slow = 1.0 second blink
Fast = 0.3 second blink

Error (yellow):

- Off: running a command (ex: tracking)
- Slow: unit in idle state. Waiting for command
- Fast: unit is reading amplitude.
- Solid: hard fault including low bus voltage

Status

- Fast: calibrating phase of tracking
- Solid: tracking phase of tracking

USB

- Off: USB port inactive or faulted (PC error)
- Slow / Fast: USB transmitting & receiving

Bat

- Off: battery is fully charged
- Fast: bus voltage too low to support operation
- On: battery charging or no battery present

Com1 (Reserved)

Com2 (Remote Probe: Tracking / Amplitude mode)

- Solid: communicating with Probe
- Slow: failing to Communicate (check wiring)
- Off: not in Tracking or Amplitude mode

VV-100 SPECIFICATIONS

Water Version: VV-100-XX-W

Water Meter Compatibility

All positive displacement, piston compound, multi-jet, single jet
Incompatible: Solid state / Ultra-sonic / Sensus Omni: see VV-200 series

Gas Version: VV-100-XX-G

Gas Meter Compatibility

All diaphragm, rotary, turbine.
Incompatible: Ultra-sonic

Data Protocols

- Modbus-TCP via Ethernet
- Modbus-RTU via Term. Block
- Telnet via Ethernet
- MQTT via Ethernet
- Pulse via Term. Block
- HTTP Publish via Ethernet
- Data Log via Onboard

Resolution (in meter revolutions)

- 1 rev Standard
- 1/100th rev Optional

Accuracy (12 month)

- Water Meter: >99%
- Gas Meter: >97%

Control and Management

- Local: via USB cable
- Remote: via Telnet / Web

Installation Limits

- -20C to 40C
- 10% - 95% RH non-condensing
- Not for hazardous locations

Main Unit and Ribbon Probe

- Indoor / Dry
- Length: 1.5 ft ribbon cable

Remote Probe

- Outdoor, immersion, burial
- Max extended: 200 ft CAT6

Power Consumption

- 300mA Max

Power Options

- 5V via USB to wall adaptor
- +5VDC 1Amp via Term. Block
- Available 12 - 24V via converter


Backup Battery: Recharg 3.7V Li-ion

- Backup life vs probe length
12hr@2 ft, 6hr@100 ft, 1hr@200 ft

Certifications

Complies with Part 15 of FCC Rules

UNIT COMPONENTS



I. SOFTWARE PREP AND HARDWARE ASSEMBLY



0. Partially Charge Battery (Optional)

Open top. Confirm battery is secure in place.
Use USB cable & wall plug adapter to wall charge unit for at least 10

1. Download Freeware: Terminal Emulator & FTDI

For **Windows OS: Tera Term** (PuTTY and other emulators may be used)

1. Go to: <https://download.cnet.com/>
2. Enter: "Tera Term" in the **Download** search bar.
3. **Download and Install** with default settings
4. Go to: <https://ftdichip.com/>
5. Navigate to **Drivers** then **VCP** and Download Driver
If Windows: Download "Setup Executable" under Comments.
6. **Reboot Laptop**

2. Assemble Unit and Connect Laptop



1. Connect **Ribbon OR Remote** Probe to Unit. Not both. (See right)
2. Connect to laptop with the mini-USB cable. LEDs blink.
3. **DO NOT** connect Ethernet port to laptop or Remote Probe.

3. Configure "Tera Term"

PROBE MUST BE CONNECTED FIRST

1. Open **Tera Term**.
2. Click **Setup** for dropdown
3. Choose **Serial Port...**
4. **Configure** as shown right
5. At **Port*** Choose the Com#.
6. Click **New Open**
7. Click Black Screen. **ENTER**
 - I. **Username:** admin **ENTER**
 - II. **Password:** admin **ENTER**

NOTE: If **Password** appears first, hit **ENTER**
8. **M> ENTER** for Command Directory
9. **T ENTER** for Tracking Directory
(try Desk-Top Simulation pg 11 to become familiar)




***If Port prompt is "grey", and unit is connected to laptop via serial port as directed above, your laptop's FTDI Driver may be missing /incorrect. Recheck above.**

****Your Tera Term configuration can be saved. At Setup dropdown: click "Save Setup"**

To Connect Ribbon Probe

VV-100-00-G
Plug Ribbon Cable
Probe into Main



To Connect Remote Probe

VV-100-0X-G
Wire Remote Probe Cat6
cable to terminal strip


1




Remove screws + cover
Find Switch **U14**
Switch 1 to "ON"
(confirm battery is secure)

2

Wire **Pigtail** to
Terminal Strip



3



Affix **Strain Relief** to side.
Zip tie **Pigtail** to **Strain Relief**

4



Connect Probe to Pigtail
using supplied Coupler

If extending the Probe's Cat6 cable:
Probe End-to-Main Unit Max Length = 200 ft
Requires additional Coupler.

INSTALLING WITH A LAPTOP



II. Tracking (Counting Meter Revolutions)

PRO TIP

- When Meter is distant from Main Unit’s final location, consider a temporary set-up at Meter with laptop to locate Probe, and discover Meter K-factor (if unknown).
- Romet, and Turbine Installations should follow this Tip.
- Honeywell Rabo Installations: contact Vata Verks

Tracking Meter Revolutions

1. Gas should flow this step*
Safely use Gas equipment per appliance instructions
2. Strap the sensor to the meter. See pg 12 for location.

3. To Calibrate or Re-Calibrate

At Tracking Menu type:

- x **ENTER** Wait for “Function complete”
Keeps last calibration & rev. count
- r **ENTER** Deletes calibration & rev. count
- t **ENTER** Calibrates and starts tracking
*If Flow=0, unit will Auto-Calibrate and Track whenever flow starts.

It takes 5 - 10 seconds to track on Rotary or Turbine Meters displaying revolution count every 5 seconds.

4. Strap or Zip Tie sensor in place. (permanently)
Zip tie Probe cable to adjacent pipe as strain relief.

If sensor moves, **Re-Calibrate**. (see above)

If discovering K-factor on-site. Start Now. Otherwise:

****** Stop Gas Flow ******

See pg 7 to Configure Communications

**Having Trouble Tracking? Refer to:
Signal Strength or Troubleshooting pg 11**

Data Displayed with Successful Tracking

SLOW METERS

```
TRACK:x
Function complete
TRACK:r
TRACK:t
Track
Start Tracking
TRACK:
P1
P2
P3
P4
P5
Signal Measured: 1850
Z Dominate
Rev=7.00 rev
Rev=23.00 rev
Rev=44.00 rev
Rev=66.00 rev
Rev=87.53 rev
Rev=108.19 rev
```

FAST METERS

```
TRACK:x
Function complete
TRACK:r
TRACK:t
Track
Start Tracking
TRACK:
P1
P2
P3
P4
P5
Signal Measured: 4538
Z Dominate
Rev=37.00 rev
Rev=83.00 rev
Rev=130.00 rev
Rev=176.00 rev
Rev=215.53 rev
Rev=235.19 rev
```

Calibrating

Tracking

Transition to Ultra Hi-Res Output
If unit equipped with this option

To Start or Stop the Display feed

- 3 **ENTER** to stop reporting to the screen
- 2 **ENTER** to re-start reporting to the screen

INSTALLING WITH A LAPTOP



III. K-Factor (Converting Revolutions to Flow Volume)

▶ Converting Revolutions to Flow Volume

K-Factor = Meter capacity in Revolutions / Unit Volume (ex: 9.2 revs / ft³)
K-Factor converts Revolution Count to Flow Volume.

A: REQUEST YOUR K-FACTOR

Nearly ALL Rotary / Turbine Meters
have been Pre-Measured.

1.

If pre-measured, we will share the K-factor with you.
Email to: info@vataverks.com



- 1) Your Name, Company, Mobile #
- 2) Installation City, state
- 3) Photo of VV-100 Barcode Label
- 4) Photo of Meter + Meter Data Plate

NOTE: One time only K-factor response per barcode.
Day-of-Install requests not recommended.

B: DISCOVER YOUR K-FACTOR

On-Site or Off-Site

Pg 7: Option 1. Calculated on the Meter

- On-Site
- Requires Gas Flow
- Requires < 10 minutes

Pg 8: Option 2. Calculated using Utility Bills

- Off-Site
- Requires 32 – 60 days.

How to Use the K-Factor

FOR MODBUS, MQTT, HTTP

To Transmit Volume

- 1) Enter K-factor in Tracking Menu
- 2) NOTE: If K-factor <1.0, See top pg 5.

Or Transmit Revolutions

- 3) Apply K-factor to your Revolution data in the Cloud

FOR PULSE

To Pulse per Standard Volume (ex: 1 pulse / 10 ft³)

- 1) Use K-factor to calculate Pulse K-factor. Enter in Pulse Menu

Or Pre-program Pulse K-Factor (ex: 10 revs / pulse)

- 2) Use K-factor to calculate resulting Volume per Pulse.

Remember to SAVE Often: 'S' ENTER

IV. Configure Communications

With K-Factor Known and Sensor Probe Strapped in Place

**TO COMPLETE THIS
INSTALLATION**

- To Configure Communication for:
MQTT, Modbus-TCP, Modbus-RTU, Pulse, HTTP Publish, Data Logging, Telnet:
See **"Data Transmission Instructions"** found at <https://vataverks.com/support/>
- If Communication is configured and data received, transfer to permanent power
 - Transfer USB Cord with Wall Adaptor to wall outlet
 - OR Optional 5VDC to terminal Strip (pg 2)

SUPPLEMENTARY INFORMATION



PRO TIP

Increasing Tracking display rate from 5 seconds to 1 second can increase accuracy of your K-factor data.

In Tracking Menu:

- + **ENTER** expands Menu
- b(space)**1.0 ENTER** sets display rate to 1/sec.
return to 5 second rate when finished

If K-Factor < 1.0

The VV-100 **requires** a K-factor of 1.0 or greater.
If K-factor is <1.0: Multiply both sides by 10.

Example: If a meter K-factor is: 0.33 Revs / ft³
Convert K-factor to: 3.3 Revs / 10 ft³.

OPTION 1: K-Factor Calculated using the Meter

K-Factor = (Revolutions from the Vata Verks Display) / (Flow Volume from the Meter Register).

Gas must be flowing for this step. Safely use gas appliance or heating system

1

TO START K-FACTOR MEASUREMENT

Simultaneously record Rev. Count from the Vata Verks Display AND take a photo of the “non-compensated” Meter Display.


NOTE: All digits on photo (including 10’s, 1’s, and black/white dial) MUST be legible. See page 12

Vata Verks Display

```
Rev=758.00
Rev=797.00
Rev=833.00
Rev=868.00
Rev=901.00
Rev=940.00
Rev=976.00
Rev=
Rev= 868.00 rev
```



Meter Display



2

*Note: More revolutions = higher accuracy K-Factor (preferably >400 revolutions).

TO STOP K-FACTOR MEASUREMENT

Simultaneously record Rev. Count from the Vata Verks Display AND take a photo of the “non-compensated” Meter Display.


NOTE: All digits on photo (including 10’s, 1’s, and black/white dial) MUST be legible. See page 12

Vata Verks Display

```
Rev=5981.00 rev
Rev=6016.00 rev
Rev=6049.00 rev
Rev=6088.00 rev
Rev=6124.00 rev
Rev=6159.00 rev
Rev=6192.00 rev
Rev=6221.00 rev
Rev= 6159.00 rev
```



Meter Display



******Gas Flow Can Be Turned OFF******

▶ **OPTION 1: K-Factor Calculated on the Meter: Continued**

1	Flow Volume from the Meter Register
	$2,676,213.65 \text{ ft}^3 - 2,676,093.55 \text{ ft}^3 = 120.10 \text{ ft}^3$
2	Revolutions from Vata Verks Display
	$6159.00 \text{ rev} - 868.00 \text{ rev} = 5291.00 \text{ rev}$
3	Revolutions / Flow Volume = K-Factor
	$5291.00 \text{ rev} / 120.10 \text{ ft}^3 = 44.05 \text{ rev/ft}^3$

▶ **OPTION 2: K-Factor Calculated Using the Utility Bill.**
No meter read or on-site laptop required.

Install Sensor. Use your archived sensor data with 1 fully Sensor Tracked Utility Bill period.	
1	$\text{Revolutions} = (\text{Rev. Count LAST day* of utility bill}) - (\text{Rev. Count 1st day* of bill})$
2	$\text{Flow Volume (ft}^3\text{)} = \text{Therms used from the monthly bill} \times 96.7 \text{ ft}^3 \text{ per Therm}$
3	$\text{Revolutions} / \text{Flow Volume (ft}^3\text{)} = \text{K-Factor (revs/ ft}^3\text{)}$

2 consecutive "Actual" Meter Reads required. No Estimated reads.

2nd Utility Bill must START after the date of installation.

*Time of Billing Period START / STOP is unknown. Use 12:00 Noon when choosing Vata Verks Sensor data. Adding subsequent months will improve accuracy.

Return to pg 5 to Apply K-Factor and complete the installation.



PRO TIP: Installing Units without a laptop On-Site

Use Simulation pg 11 to familiarize before sending to field.



PRO TIP: Installing Units with Remote Probe

Temporarily set up at Meter to confirm tracking.

A laptop is suggested for larger meters and all Turbines.

Setting up the Main Unit

1. Unit **MUST** be Assembled and Configured Off-Site (see pg 3)
See Instructions: Configuring Data Transmission at:
<https://vataverks.com/support/>
2. Strap Probe to meter. Refer to **Sensor Placement Maps** (pg 12).
3. Connect Power: USB wall adaptor OR 5VDC to terminal strip.
LEDs will be ON.
4. **Gas MUST flow through Meter THIS STEP.**
Gently depress **Reset** with paperclip. LEDs will blink off. (pg 2)
With **Reset**, Unit will auto-Calibrate then track with flow
(If Flow=0, unit will Auto-Calibrate and Track when flow starts)
5. **COM2** LED solid if Remote Probe is Communicating.
Status LED blinks if Calibrating. Solid if Tracking Flow
**** **Gas Flow Can be Turned OFF** ****
6. Zip Tie Probe Cable to pipe as strain relief. Permanently
7. Finish: Affix Main Unit in a dry location.
8. If MQTT, Modbus, HTTP: Connect Ethernet cable to Gateway
9. If Pulse: Wire twisted pair from terminal strip to Pulse counter
10. If unit Sensor Probe was unplugged, or unit lost power:
Reset the device. Repeat steps 4, 5, 6.
11. Confirm data is being received.
12. Discover K-Factor (see below)



Failure to Calibrate?

- Option 1** Reposition Probe: try again.
Repeat Steps 4 through 12
- Option 2** A Telnet connected colleague can help identify the strongest magnetic field location ([pg 11](#))

Options to Discover K-Factor without a Laptop*

- A. From Vata Verks K-factor archive. (pg 5)
- B. Using Monthly Bills * (pg 8)
- C. Real-time tracking data received in office (pg 7)
with Simultaneous meter reads in the field.
- D. Archived tracking data synchronized (pg 5)
with time stamped photos of meter register*

**If meter resolution is 100 ft³, high flow volume is required to reduce error.*

Supplementary Information -

COMMAND MENU REFERENCE

****MAIN MENU****

- M** - Main Menu
 - T** - Tracking menu **SEE BELOW**
(to configure for Modbus, MQTT, HTTP Publish)
 - C** - Communication menu *(to configure for Modbus, MQTT, Telnet)*
 - N** - Network menu *(to configure for Pulse)*
 - P** - Pulse Output menu
 - Z** - Device maintenance menu **SEE BELOW**
 - g** - Logout
 - x** - Exit current function
 - S** - Save configuration **SAVE OFTEN**
- Some configuration parameters require a reset to take effect
- M** – Return to Main Menu

T ENTER

****TRACKING MENU****

- a** - Signal Strength (requires flow) *measure magnetic field strength*
 - t** - Start tracking (requires flow)
 - x** - Stop Tracking or Signal Strength
 - r** - Reset tracker to 0, deletes calibration
 - k** - Enter meter K factor rev/unit volume (k xxx.xxx) *for entering k factor. Will not accept k-factor <1.0. see pg 7.
K-factor can be any unit of volume. This takes note of the choice.*
 - v** - Set Units (gal, ft3, m3, rev) (v gal)
 - 2** - Start reporting data to screen
 - 3** - Stop reporting data to screen
 - +** - Show Advanced Functions *So many other features*
 - S** - Save configuration **SAVE OFTEN**
- Some configuration parameters require a reset to take effect
- M** – Return to Main Menu

Z ENTER

****MAINTENANCE MENU****

- a** - Start Tracking on powerup *default is enabled.*
 - c** - Display current configuration – all *useful information*
 - v** - Display Version Information *useful information: Serial Number and firmware build
displays programmed time*
 - b** - Display device info and battery status
 - R** - Reset Board **soft Reset: saves tracking+count. (hard button Reset does not)**
(Note: Push button Reset deletes Calibration and Tracking)
 - f** - Restore factory defaults
 - r** - Reload last saved configuration
 - p** - Save path file
 - m** - Record signal strength (SEE INSTR)
 - w** - Enable/Disable Web Server *Default is enabled*
 - u** - Set device username and password
 - t** - Set Time of day 24Hr format (t yyyy:mm:ddThh:mm:ss) *programming time*
 - k** - Unlock features *admin Use*
 - S** - Save configuration **SAVE OFTEN**
- Some configuration parameters require a reset to take effect
- M** – Return to Main Menu



Trouble / Causes / Corrections

1. **Attempting to Track**
Displays: "Start Tracking"
Does not display: P1, P2 etc showing calibration.
 - a. No flow through meter?
 - b. Sensor not strapped to meter?
 - c. Magnetic Field too weak: Find Stronger (pg 12)
 - d. Meter incompatible
2. **Attempting to Track**
Displays: "Start Tracking"
Display repeats over and over P1, P2, P3, P4, P5
 - a. Flow happening, but magnetic field too weak.
 - b. Find Stronger Field (see Right)
3. **Attempting to Track**
Does not display "Start Tracking"
 - a. Repeat the steps x, r, t (see pg 4)
 - b. Wait for "Function Complete" after "x", before "r"
4. **Will not track. Though Magnetic Field is strong.**
 - a. Go to Z Menu, and Reset "R" the device.
5. **"Sensor Stall" warning**
 - a. Check that Sensor is correctly wired.
 - b. Reset the device
6. **"Remote Sensor Not Found" warning or COM2 LED blinking**
 - a. Check that Sensor is correctly wired
 - b. Go to Z Menu, and Reset "R" the device.
7. **LED's are OFF, though Power is ON**
 - a. Unscrew top, Find Switch U15, Confirm all OFF.
 - b. Reset the Unit with Push Button
8. **K-Factor Entry on Tracking Menu:**
Displays: ****Invalid Data Entry****
 - a. K-factor <1.0 is not accepted by VV-100
 - b. Use 10X. Ex: 0.3 rev/ft3 = 3.3 rev / 10 ft3
 - c. Enter 3.3, and take note of 10 ft3.
9. **Forgot Password or Username**
 - a. **Contact Vata Verks for instructions**

Desk Top Simulation

Sensor function simulated using Earth's magnetic field.

From Tracking Menu:

Simulate Tracking

- A) Holding probe in hand
- B) x ENTER to stop function
- C) r ENTER to delete calibration
- D) t ENTER to calibrate / track
- E) Roll sensor back and forth (as below)



Measure Magnetic Fields

- A) a ENTER to measure field
- B) Move sensor or pass objects by probe

Find Meter's Strongest Signal Location

Gas Flow Required

At Tracking Menu:

a ENTER measures field strength

Seek highest last number in the series.

Hold Probe to meter for multiple readings then move to new location.

If Output is:

- A) 9,11,9,25 no signal or no flow
- B) 27,5,34,175 too low
- C) 111,47,267,382 >275 is good
- D) 0,630,0,2500 >2000 can be too strong*

*If too strong, either:

- A) w ENTER disables Boost
- B) Move Probe to weaker location


Found a suitable location?

Repeat Tracking pg 4

Supplementary Information -

SENSOR PLACEMENT / METER READING

Recommended Probe Location



Rotary:
Between Chamber
and Register



Rotary:
Between Chamber
and Register



SPECIAL CASE
Dresser D800 / D1000
Rotary Meter



Turbine
Sensus / Equimeter
Auto Adjust Mach II



Turbine
Honeywell / Elster
GT/GTS/GTX

Place chip top of register
attachment flange

Honeywell Rabo Rotary Meters
Contact Vata Verks: info@vataverks.com


Strapping Probe to Meter

- Rubber strap (included in kit)
AND / OR your own:
- Zip ties (do not damage probe)
- Adhesive strain reliefs

Still Need help
Send Question and Photo to
info@vataverks.com

How to Read a Rotary Meter

- Use the “Non-Compensated Volume” reading.
- Dresser: Use a light to see 10’s and 1’s. (see below).
- Snap photo of the register and read from the photo.
- Dresser: Each “hash” mark on right side = 0.2 ft³.
 - Rollover (X.00 ft³) = main hash aligns with fixed hash.
 - Estimate to the 2nd decimal place. (ex: 3,403,721.36 ft³)



Meters with 100 ft³ max Resolution

100 ft³ is not normally enough Resolution.

- Seek K-Factor from Vata Verks. (see pg 5)
- Use monthly billing to calculate k-factor. (see pg 8)
- Un-corrected totalizer may exist and have higher Res.
- Mercury Instruments: Press button to **Hi-Res Cor /Uncor**
- Use Rollover. 100 ft³ Rollover = 100.00 ft³ (see pg 7)
- Increase Denominator: >10,000 ft³, max error = 2%



When Compensated & Non-Compensated
output is greatly different the utility may be
using a high pressure feed.

Confirm K-factor with the Monthly Bill